# CODESOFT

## CS-200 barcode scanner quick guide

☞ A standard packing includes a scanner, a USB cable and a CD (or a user manual).

☞ Accessories include a stand, a RS232 cable, a 5VDC adaptor cable.

☞ Use a piece of dry and soft cloth when cleaning the scanner.

### Parts of the scanner



① LED

② Beeper

③ Exit window

④ Trigger

⑤ Release-hole of the cable

⑥ Cable interface port

### Installing the cable

1. Switch off the host;

2. Refer to the below pictures, connect the host with the scanner based on different cables;

3. Ensure that all connections are secure.

4. Switch on the host system.　If installation is successful, the beeper will beep and LED will light.



USB cable　　　　　　RS232 cable

### Removing the cable

1. Find the release-hole.

2. Insert a thin wire into the hole and pull out the cable gently.

### Default value initialization and Firmware version list



Default value initialization　　　　Firmware version list

### Programming instruction and example

Scan "SETUP"
↓
Scan "Option bar code"
↓
Scan "the 1st character of option"
↓
Scan "the 2nd character of option"
↓
Scan "END"



Example: to set Flow control to be XON/XOFF.